




	SCALE: NTS	DATE: 04-12-10	DRAWN BY: TOG	 PREISER SCIENTIFIC, INC. 94 OLIVER STREET ST. ALBANS, WV 25177 USA PHONE: (304) 727-2902 FAX: (304) 727-2932 www.preiser.com
	APPROVED BY: KW		CHECKED BY:	
USED IN ASSEMBLY: HARD GROVE GRINDABILITY		115V 60 Hz ASSEMBLY		Z90-9300-01

Part No:	Description	Diagram Number
Z90-9300-03	Grindability Ball Set, 1" (8)	1
90-9300-04	Upper Grinding Element	2
Z90-9300-05	Lower Grinding Element	3
Z90-9300-07	Timing Belt 230V	4
Z90-9300-12	Shaft	5
Z90-9300-14	Driven Pulley with Trip Arm	6
Z90-9300-16	On/Off Switch	7
Z90-9300-17	Thermal Overload 6.2 230V	8
Z90-9300-18	Brass Bushing (2)	9
Z90-9300-19	Grease Seal	10
Z90-9300-13	Drive Pulley for 230V/115V 60Hz	11
Z90-9300-23	Drive Pulley for 230V 50Hz	11
Z90-9300-26	1/2" Straight Connector	12
Z90-9300-27	90° 1/2" Connector	13
Z90-9300-28	Bolt and Wing Nut (2)	14
Z90-9300-36	Motor 230V 50Hz	15
Z90-9300-30	Motor 230V 50Hz	15
Z90-9300-31	Gear Reducer 230V	16
Z90-9300-32	Belt Guard 230V	17
Z90-9300-34	Bushing, Tapered 1" 230V	18
Z90-9300-37	Weight (4)	19
Z90-9300-38	Proximity Sensor	20
Z90-9300-39	Counter	21
Z90-9300-09	Timing Belt 115V	22
Z90-9300-15	Bushing, Tapered 3/4" 115V	24
Z90-9300-25	Thermal Overload 11.0	25
Z90-9300-29	115V Motor w/ Speed Reducer	26
Z90-9300-35	Belt Guard 115V	27